



**TWF**



Pages  
2-9  
+  
16-23



**TLF**






Pages  
10-23






1a





1b




1c





2





3








4






5



6





7




7 x 

8










9a








9b








1a




1b







4






5




6




7



8






9






Page 16

10








11











12





13




14






15





16




17





18





19






20




21







22



23



24



<b>AR:</b> VELUX Argentina S.A. 0 114 711 5666	<b>IE:</b> VELUX Company Ltd. 1800 409 750
<b>AT:</b> VELUX Österreich GmbH 02245/32 3 50	<b>IT:</b> VELUX Italia s.p.a. 045/6173666
<b>AU:</b> VELUX Australia Pty. Ltd. (02) 9550 3288	<b>JP:</b> VELUX-Japan Ltd. 0570-00-8145
<b>BA:</b> VELUX Bosna i Hercegovina d.o.o. 033/626 493, 626 494	<b>LT:</b> VELUX Lietuva, UAB (85) 270 91 01
<b>BE:</b> VELUX Belgium (010) 42.09.09	<b>LV:</b> VELUX Latvia SIA 67 27 77 33
<b>BG:</b> VELUX Bulgaria EOOD 02/955 95 26	<b>NL:</b> VELUX Nederland B.V. 030 - 6 629 629
<b>BY:</b> VELUX Roof Windows FE. (017) 217 7385	<b>NO:</b> VELUX Norge AS 22 51 06 00
<b>CA:</b> VELUX Canada Inc. 1 800 88-VELUX (888-3589)	<b>NZ:</b> VELUX New Zealand Ltd. 09-6344 126
<b>CH:</b> VELUX Schweiz AG 0848 945 549	<b>PL:</b> VELUX Polska Sp. z o.o. (022) 33 77 000 / 33 77 070
<b>CL:</b> VELUX Chile Limitada 2-231 18 24	<b>PT:</b> VELUX Portugal, Lda 21 880 00 60
<b>CN:</b> VELUX (CHINA) CO. LTD. 0316-607 27 27	<b>RO:</b> VELUX România S.R.L. 0-8008-83589
<b>CZ:</b> VELUX Česká republika, s.r.o. 531 015 511	<b>RS:</b> VELUX Srbija d.o.o. 011 3670 468
<b>DE:</b> VELUX Deutschland GmbH 0180-333 33 99	<b>RU:</b> VELUX Rossia ZAO (495) 737 75 20
<b>DK:</b> VELUX Danmark A/S 45 16 45 16	<b>SE:</b> VELUX Svenska AB 042/20 83 80
<b>EE:</b> VELUX Eesti OÜ 621 7790	<b>SI:</b> VELUX Slovenija d.o.o. 01 724 68 68
<b>ES:</b> VELUX Spain, S.A. 91 509 71 00	<b>SK:</b> VELUX Slovensko, s.r.o. (02) 33 000 555
<b>FI:</b> VELUX Suomi Oy 0207 290 800	<b>TR:</b> VELUX Çatı Pencereleri Ticaret Limited Şirketi 0 216 302 54 10
<b>FR:</b> VELUX France 0821 02 15 15 0,119€ TTC/min	<b>UA:</b> VELUX Ukraina TOV (044) 490 5703
<b>GB:</b> VELUX Company Ltd. 0870 380 9593	<b>US:</b> VELUX America Inc. 1-800-88-VELUX
<b>HR:</b> VELUX Hrvatska d.o.o.. 01/5555 444	
<b>HU:</b> VELUX Magyarország Kft. (06/1) 436-0601	